



Material Safety Data Sheet

PT. APLUS PACIFIC

Jl. Prabu Siliwangi Km.3 Pasir Jaya

Jatiuwung – Tangerang 15135

Section I

IDENTITY (AS USED ON LABEL AND LIST)

Screw-TRUSS

Formula: Proprietary Blend

Date Prepared:

9/18/2002

Section II COMPONENT INFORMATION

[Specify Chemical Identity; Common Name(s)]

CAS #S	OSHA PEL	ACGIH TLV	OTHER LIMITS	% (OPTIONAL)
--------	----------	-----------	--------------	--------------

Section III -Section III-Physical/Chemical Characteristics

Boiling Point:	N/A	Specific Gravity(water-1):	0.92
Vapor Pressure(mm hg.)	Undetermined	Melting Point:	168F
Vapor Density(AIR=1)	Undetermined	Evaporation Rate: (BUTYL ACETATE=1)	N/A
Solubility in Water:	Insoluble		
Appearance & Odor:	Yellow to Brown Solid Wax		

Section IV -FIRE AND EXPLOSION HAZARD DATA

Flash Point:	Undetermined	Method Used:	Undetermined	LEL:	N/A
Flammable Limits:	Undetermined	UEL:	N/A		
Extinguishing Media:	Foam, water, dry chemical, CO2.				
Special Fire Fighting Procedures:	None				

Section V -Reactivity Data

Stability:	Unstable	<input type="checkbox"/>	Stable	<input checked="" type="checkbox"/>
Incompatibility (Material to Avoid):	None			
Hazardous Decomposition or byproducts:	Carbon monoxide and carbon dioxide.			
Hazardous Polymerization:	Will not occur	<input checked="" type="checkbox"/>	Will Occur	<input type="checkbox"/>
Conditions to Avoid:	None Known			

Section VI -Section VI HEALTH HAZARD DATA

Routes of Entry Inhalation: Skin X Ingestion: X

Health Hazards (Acute and Chronic): None Known

Threshold Limit Value: Undetermined

Carcinogenicity:	NTP:	I.A.R.C monographs:	OSHA REGULATED:
Not Listed	Not Listed	Not Listed	Not Listed

Signs and Symptoms of exposure: None Known

Medical Conditions Generally Aggravated by Exposure:

Emergency and First Aid Procedures:	Inhalation Exposure -	N/A
	Eye Contact -	Wipe Clean
	Skin Contact -	Wash with soapy water.
	Internal -	Contact physician immediately.

Section VII -Precaution for safe Handling and Use

Steps to be taken in case Material is Released or spilled: Scrape off Surface

Waste Disposal Method: Dispose of according to all Federal, State & Local Regulations.

Precautions to be taken in Handling and Storing: Store in a cool dry place.

Other Precautions: Labeling - None

Section VIII -Control Measures

Respiratory Protection (Specify Type): None

Ventilation:	Local Exhaust:	xx	Mechanical (General):	Special:	Other:
--------------	----------------	----	-----------------------	----------	--------

Protective Gloves: N/A

Eye Protection: Safety Glasses

Other Protection clothing or equipment: None

Work/Hygienic Practices: Use good work practices.