

PT. APLUS PACIFIC

JL. PRABU SILIWANGI KM. 3 PASIR JAYA JATIUWUNG – TANGERANG 15135

Section I							
INDENTITY (AS US	ED ON LABEL AND	LIST)					
Screw - TRUS	S						
				Formula:	Proprietary E	Blend	
				Date Prepa			
				9/18/2002			
Section II COMPONENT INFORMATION							
[Specify Chemical Identity				ACGIH	OTHER		
[Opening Chemical racinity	,,(-),	CAS #'S	OSHA PEL	TLV	LIMITS	% (OPTIONAL)	
		21.12 2				/	
Section III -Section	on III-Physical/Chem	ical Characteris	stics .				
Boiling Point: N/A			,	Specific Gravity(water-1):		0.92	
				op come cramy (me			
Vapor Pressure(mm hg.)	Undetermined			Melting Point:		168F	
3)							
Vapor Density(AIR=1)	Undetermined			Evaporation Rate: N/A		N/A	
7				(BUTYL ACETATE=1)		<u> </u>	
Solubility in Water:	Insoluble			(======================================	,		
,						•	
Appearance & Odor:	Yellow to Brown S	olid Wax				•	
Section IV	-FIRE AND EXPLOS	SION HAZARD	DATA				
Flash Point: Undetern	nined Method Used:	Undetermined	LEL:	N/A			
Flammable Limits: Undetern	nined		UEL:	N/A			
Extinguishing Media:	Foam, water, dry o	hemical, CO2.					
Special Fire Fighting Procedures: None							
Section V -R	eactivity Data						
Stability:	Unstable		Stable	x			
,							
Incompatibility (Material to Avoid):	None						
Hazardous Decomposition or bypi		Carbon monoxide and carbon dioxide.					
F 22 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2							
Hazardous Polymerization:		Will not occur	x	Will Occur			

Conditions to Avoid:

None Known

Section VI -Section VI HEALTH HAZARD DATA

Routes of Entry Inhalation: Skin Ingestion: Health Hazards (Acute and Chronic): None Known Threshold Limit Value: Undetermined Carcinogencity: NTP: I.A.R.C monographs: OSHA REGULATED: Not Listed Not Listed Not Listed Not Listed Signs and Symptoms of exposure: None Known Medical Conditions Generally Aggravated by Exposure: Emergency and First Aid Procedures: Inhalation Exposure -N/A Eye Contact -Wipe Clean Skin Contact -Wash with soapy water. Internal -Contact physician immediately. Section VII -Precaution for safe Handling and Use Steps to be taken in case Material is Released or spilled: Scrape off Surface Waste Disposal Method: Dispose of according to all Federal, State & Local Regulations. Precautions to be taken in Handling and Storing: Store in a cool dry place. Other Precautions: Labeling - None Section VIII -Control Measures None

Respiratory Protection (Specify Type):

Ventilation: Local Exhaust: Mechanical (General): Special: Other: хх

Protective Gloves: N/A

Eye Protection: Safety Glasses

Other Protection clothing or equipment: None

Work/Hygienic Practices: Use good work practices.